

Title: Assessment of Vibration severity at NTPC Rihand Super Thermal Power Station (Stage 2 and Stage 3) SSP 427

Duration: 10 months

Deliverables:

Submission of test report based on the studies

Significant Achievements:

1. Measurement of vibration levels on selected machine foundation structures including TG foundation decks, TG Halls, ID Fans, FD Fans, PA Fans, DM Plants and Crusher house at Rihand Super Thermal Power Station (Stage 2 (Unit 3 & Unit 4) and Stage 3 (Unit 5 & Unit 6)) have been completed
2. Vibration severity based on national and international standards are assessed and recommendations have been made



Team:

Dr. P. Kamatchi
Mrs. R. Sreekala
Dr. Mohit Verma
Dr. C. Bharathi Priya
Dr. S. R. Balasubramanian
Shri. J. C. Sunil

Date: 24-06-2026